



Announcement Regarding the Discontinuation of MOS IC Products

Thank you for using SANYO semiconductor products.

The following SANYO semiconductor products have been discontinued.

Please check this list carefully and contact your SANYO semiconductor sales representative if you have any questions.

1. Affected products list

Affected products	Affected products	Affected products
LC72131	LC72131MD	LC72131MD-UKS-TLM-E
LC72131D	LC72131MD-MPB-E	LC72131M-MPB-E
LC72131D-E	LC72131MD-TE-L	LC72131M-TE-L
LC72131D-N	LC72131MD-TLM	LC72131M-TLM
LC72131D-N-E	LC72131MD-TLM-E	LC72131M-TLM-E
LC72131D-U	LC72131MD-TRM	LC72131M-TRM
LC72131D-Z	LC72131MD-TRM-E	LC72131M-UMIT-TLM
LC72131-E	LC72131MD-UKS-MPB	LC72131M-UMIT-TLM-E
LC72131M	LC72131MD-UKS-TLM	

2. Reason for discontinuation

Aging of production equipment and rationalization and unification of product lineup.

3. Replacement products

LC72131K
LC72131KM

4. Date of Implementation

End of March 2010.

Please contact your SANYO semiconductor sales representative if you have any questions or need any technical documentation.