



Announcement Regarding the Discontinuation of BIP IC Products

Thank you for using SANYO semiconductor products.
The following SANYO semiconductor products have been discontinued.
Please check this list carefully and contact your SANYO semiconductor sales representative if you have any questions.

1. Affected products

See the table “Affected products list” on the following pages.

2. Reason for discontinuation

Rationalization and unification of the product lineup.

3. Date of Implementation

End of November 2010.

Please contact your SANYO semiconductor sales representative if you have any questions or need an technical documentation.

Affected products list

Affected products	Replacement products	Affected products	Replacement products
LA0150CS	-	LA4605	-
LA0224CS	LA0225CV	LA4611	-
LA1651C-X1	LA1654C	LA4744	-
LA1651C-X2	LV2600C	LA4743B	-
LA1652C-X1	LA1654C	LA4743BL	-
LA1652C-X2	LA1654C	LA47504	-
LA1652FN	LA1654FN	LA47505	-
LA1780M	-	LA47506	-
LA1780ML	-	LA47508	-
LA1784M	-	LA47510	-
LA1814M	LA1827	LA47512	-
LA1831	-	LA47512L	-
LA1832	-	LA47514	-
LA1832M	-	LA47515	-
LA1832ML	-	LA47516	-
LA1833L	-	LA47532	-
LA1833N	-	LA47534	-
LA1835	-	LA4743J	-
LA1836	LA1837	LA4743K	-
LA1836L	LA1837	LA4743KL	-
LA1836M	LA1837	LA4763	-
LA1838	-	LA4810M	-
LA1838L	-	LA49032H	-
LA1837NL	-	LA49032H-EB	-
LA2352M	-	LA49032HL	-
LA2360M	-	LA49101H	-
LA2655V	-	LA49101HL	-
LA2657M	-	LA4915	-
LV1035ML	-	LA4917H	-
LA2785	-	LA4919N	-
LA2785L	-	LA4930M	-
LA2786	-	LA5624H	-
LA2786L	-	LA5636M	-
LA2787	-	LA5643	-
LA2900M	-	LA5645M	-
LA2901V	-	LA5647H	-
LA2902V	-	LA5648	-
LA4108R	-	LA5661M	-
LA4220	-	LA5662M	-
LA4224	-	LA5663V	-
LA42351	-	LA5664M	-
LA42351HK	-	LA5669T	-
LA4301	-	LA5679T	-
LA4302T	-	LA5679LP	-
LA4303	-	LA5680T	-
LA44403	-	LA5681FN	-
LA44403L	-	LA5681T	-

Continued on next page.

Continued from preceding page.

Affected products	Replacement products	Affected products	Replacement products
LA5683T	-	LA6593	-
LA5734MP	-	LA6703M	-
LA5751MP	-	LA6705UC-WP	-
LA5752MP	-	LA70001L	-
LA5753	-	LA70001LL	-
LA5753MP	-	LA70011LL	-
LA5754	-	LA70016	-
LA5754MP	-	LA7104M	-
LA5779N	-	LA7106M	-
LA5777MP	-	LA7108M	-
LA5779L	-	LA7109	-
LA5779MPL	-	LA7134M	-
LA5781FN	-	LA7135AM	-
LA5782T	-	LA7138M	-
LA5796CL	-	LA7157M	-
LA6505	-	LA7158M	-
LA6508H	-	LA7195	-
LA6515	-	LA7207	-
LA6511	-	LA7208GL	-
LA6525M	-	LA7265W	-
LA6532M	-	LA7277M	-
LA6537	-	LA73051	-
LA6537M	-	LA73052	-
LA6538T	-	LA73056	-
LA6544H	-	LA7337	-
LA6546H	-	LA7337L	-
LA6548	-	LA7339A	-
LA6548D	-	LA7357	-
LA6551	-	LA7357M	-
LA6556L	-	LA7358	-
LA6557H	-	LA7358M	-
LA6558	-	LA7359	-
LA6559	-	LA7395	-
LA6562	-	LA7438AM	-
LA6563	-	LA7440	-
LA6564H	-	LA7565N	-
LA6567H	-	LA7565BM	-
LA6567HL	-	LA7565BMK	-
LA6568	-	LA7565EML	-
LA6570	-	LA7565KM	LA7567BVA
LA6572	-	LA7566	LA7567BVA
LA6574D	-	LA7566ML	LA7567BVA
LA6574H	-	LA75660V	LA75600VA
LA6575H	-	LA75663M	LA7567BVA
LA6576	-	LA75665M	LA7567BVA
LA6576L	-	LA7567NM	LA7567BVA
LA6582T	-	LA75675M	LA75600VA

Continued on next page.

Continued from preceding page

Affected products	Replacement products	Affected products	Replacement products
LA7566NS	LA7567BVA	LA9612T	-
LA7566S	LA7567BVA	LA9613T	-
LA75676NVA	LA75600VA	LA9616GB	-
LA7569	-	LA9700M	-
LA75693M	LA75600VA	LB11650H	LV8760T
LA75693VA	LA75600VA	LB11665V	-
LA7583N	-	LB11676V	-
LA7642N	-	LB11681H	-
LA7642NM	-	LB11684H	-
LA7670K	-	LB11684V	-
LA7675	-	LB11690	-
LA7693	-	LB11690H	-
LA7832	LA7833	LB11691	-
LA7833-S	LA7833	LB11691H	-
LA7837	LA7838	LB11692H	-
LA7838-K	-	LB11692JH	-
LA7845	-	LB11693	-
LA7860	-	LB11695M	-
LA7860M	-	LB11699H	-
LA7865H	-	LB11816V	-
LA7865M	-	LB11819V	-
LA79503V	-	LB11820M	-
LA79510M	-	LB11823M	-
LA7973M	-	LB11824M	-
LA7985	-	LB11827	-
LA8190TT	-	LB11872V	-
LA8511	-	LB11880	-
LA8511N	-	LB11885	-
LA8638NV	-	LB11885J	-
LA8638NVL	-	LB11891V	-
LA8638V	-	LB11882A	-
LA8662V	-	LB11882J	-
LA8677V	-	LB11883N	-
LA9230M	LA9242	LB11886NA	-
LA9230MT	LA9242	LB11908NV	-
LA9235M	LA9242	LB11906V	-
LA9240M	LA9242	LB11908V	-
LA9240ML	LA9242	LB11917	-
LA9241M	LA9242	LB11945H	-
LA9241ML	LA9242	LB11947	-
LA9251M	LA9242	LB11947L	-
LA9251MHK	LA9242	LB11950GL	-
LA9511W	-	LB11951W	-
LA9511WL	-	LB11951WA	-
LA9610T	-	LB11952W	-
LA9611GB	-	LB11954FN	-
LA9611T	-	LB11954W	-

Continued on next page.

Continued from preceding page

Affected products	Replacement products	Affected products	Replacement products
LB11955WA	-	LB8652LP	-
LB11956FN	-	LB8652LPL	LV8052
LB11956W	-	LB8653C-X2	LV8052
LB11960FV	-	LB8653FN	-
LB11965M	-	LB8653T	-
LB11966M	-	LB8654V	-
LB11680H	-	LB8655T	-
LB11971H	-	LB8658FN	-
LB11972V	-	LB8659FN	LV8054
LB11975	-	LB8659PL	LV8054
LB11975L	-	LB8659PLL	LV8054
LB11981	-	LB8682PL	-
LB11990FN	-	LB8683CL	-
LB11990W	-	LB8684CL	-
LB11993FN	-	LB8688LF	-
LB11993W	-	LA42110	-
LB11995	-	LA43103	-
LB11995H	-	LA43203	-
LB11995LL	-	LA47035P	-
LB11998V	-	LA8101LP	-
LB1800CL	-	LA8580NW	-
LB1801CL	-	LB11925	-
LB1820	-	LB11977V	-
LB1822	-	LB8502PM	-
LB1824	-	LB8688C-WP	-
LB1824SF	-	LB8681CL	-
LB1825	-		
LB1839M	-		
LB1872	-		
LB1872K	-		
LB1877V	-		
LB1897	-		
LB1902C	-		
LB1921	-		
LB1921F	-		
LB1924	-		
LB1924A	-		
LB1935C-X2	-		
LB1931T	-		
LB1941CL	-		
LB1971V	-		
LB1994M	-		
LB8500M	-		
LB8502M	-		
LB8650T	-		
LB8651T	-		
LB8652T	LV8052		