



# Announcement Regarding the Discontinuation of MOS IC Products

Thank you for using SANYO semiconductor products.

The following SANYO semiconductor products have been discontinued.

Please check this list carefully and contact your SANYO semiconductor sales representative if you have any questions.

### 1. Affected products list

Affected products	Replacement products
LC78690NW-E	-
LC78690NW-UPHI-E	-
LC78690NW-LR-UHK-E	-
LC78690NW-LR-USH-E	-
LC78690NW-UMTS-E	-
LC78690NW-LR-UMTS-E	-
LC78690NW-UTOM-E	-
LC78690NW-LR-E	-
LC78691NE-UM-E	-
LC78691NE-UDA-E	-
LC78691NE-LR-UDA-E	-

### 2. Reason for discontinuation

Wafer supply from the outsourcing company ends.

### 3. Date of Implementation

March 2010.

Please contact your SANYO semiconductor sales representative if you have any questions or need any technical documentation.