



# Announcement Regarding the Discontinuation of MOS IC Products

Thank you for using SANYO semiconductor products.

The following SANYO semiconductor products have been discontinued.

Please check this list carefully and contact your SANYO semiconductor sales representative if you have any questions.

### 1. Affected products list

Affected products	Affected products
LC78601RE-8615	LC78602RE-8616DN
LC78601RE-8615D	LC78602RE-8616DN-E
LC78601RE-8615DM	LC78602RE-8616N-E
LC78601RE-8615N	LC78602RE-8622
LC78601RE-8615N-E	LC78602UE
LC78602HKE-8612	LC78602YE
LC78602HNE-8612D	LC78603E-8626
LC78602HNE-8612DY	LC78603E-8628
LC78602HNE-8612Y	LC78603E-8628-E
LC78602RE-8616	LC78604E-E
LC78602RE-8616D	LC78604E-D-E
LC78602RE-8616D-E	LC78605E-D-E
LC78602RE-8616DM	LC78605E-E
LC78602RE-8616DM-E	

### 2. Reason for discontinuation

Rationalization and unification of the product lineup.

### 3. Replacement products

None.

### 4. Date of Implementation

March 2010.

Please contact your SANYO semiconductor sales representative if you have any questions or need any technical documentation.